





Corn Carrier



Parts List

Step	Qty	Description
1	1	Axle 8
1	2	Bushing - 1/2
1	2	Bushing
1	1	90 degree Adapter
2	1	Gear - 8 Tooth
2	1	90 Degree Connector
2	1	Bushing - 1/2
2	1	Axle Pin
3	2	Gear - 40 Tooth
3	2	Bushing
4	2	Brick 1x16 - holes
5	2	Plate 2x8 - holes
6	8	Pin
7	1	Axle 8
8	1	Crown Gear - 24 Tooth
8	2	Bushing
9	1	Axle 10
9	2	90 Degree Connector
9	1	Bushing
9	1	Axle Pin
10	1	Gear - 24 Tooth
10	1	Gear - 16 tooth
11	37	Chain Link
12	7	Crop Bale

